

## To Whom it may concern

<b>SERVICE BULLETIN – Poseidon EBS MkII</b>				
Valid from:	2024-06-17	Approved by:	Jonas Brandt	Revision: 1.0
Valid to:	N/A	Created by:	Jörgen Nilsson	
Document ID:	2024-06-17-0009-024_Service_kits.pdf			
Valid for article number:	5000-015 / 0005-272 / 0005-329			
Valid for versions:	14 and later			
Applies to service manual version:	1.9.5			

### Background.

With the introduction of the all black LP hose and swivel (0130-060, 0130-057 and 0130-062) a new service kit was need, as the o-rings used in these swivels differs from the one used in the chromed swivel.

### Recommendation

Before ordering service kits for your EBS MkII systems, check what type of swivel and LP hose your systems have, to ensure you order the correct service kits.

### Changes

Service kit 0009-024 Service kit EBS MKII remains unchanged. This is what you order if your EBS MkII system uses the chromed swivel and hoses.

If your EBS MkII system uses the black swivel and LP hoses, you order the new service kit 0009-025 Service kit EBS MKII black swivel & hose. It has a new service kit for the black Swivel and LP hoses: 0009-028 Service Kit Black Swivel and Hoses EBS.

This change does not affect the actual servicing of the EBS MkII unit and service instructions for both the chromed and black swivels and the correct article numbers for the different service kits have been added to service manual v 1.9.5.



Jörgen Nilsson – Quality Manager.